


## CALIFORNIA ENVIRONMENTAL QUALITY ACT **Notice of Exemption**

State Cle 1400 Ten	Land Use and Climate Innovation aringhouse th Street Department of Conservation and Development 30 Muir Road Martinez, CA 94553		
□ County C	lerk, County of Contra Costa		
Project Title:	FCZ 3B Grayson Creek Bank Erosion Repair, WO9M08, CP#25-13		
Project Applicant:	Contra Costa County Flood Control & Water Conservation District, 255 Glacier Drive, Martinez, CA 94553, (925) 313-2000, Contact: Alex Nattkemper (925) 313-2364 <a href="mailto:alex.nattkemper@pw.cccounty.us">alex.nattkemper@pw.cccounty.us</a>		
Project Location:	cation: Maintenance road on the western bank of Grayson Creek, approximately 380 feet so of Golf Club Road, Pleasant Hill; APN 153-040-009		
Lead Agency:	Department of Conservation and Development, 30 Muir Road, Martinez, CA 94553		
Contact Person: Syd Sotoodeh (925) 655-2877 syd.sotoodeh@dcd.cccounty.us			
gravel maintenance surface flow during a erosion has narrowe from accessing a se into the channel bar which will be comparative seed mix. The slopes. Temporary of the top of the channel surface flow coming diameter pipe will be vegetation trimming in 2026 or 2027. We Appropriate best maprotect the creek. Appropriate comparation will be suffaced by the comparation of the channel surface flow coming diameter pipe will be suffaced by the comparation of the channel surfaced by	road and creek channel bank that eroded as a result of the road being over-topped by a storm event. The erosion is approximately 19 feet long, 9 feet wide and 4 feet deep. This d the usable width of the existing maintenance road and prevents County Maintenance staff ction of Grayson Creek. The repair will consist of cutting an approximately 6-foot-deep key had and placing rock slope protection (RSP) and engineered fill to protect against erosion, acted up the slope. Topsoil will be placed over the engineered fill and hydroseeded with a e bank repair will extend approximately 35 feet long to conform to the adjacent channel lewatering of the creek may be necessary during construction. The maintenance road along all bank will be restored to pre-existing condition. To lessen the impact of concentrated storm from the neighboring property and prevent further erosion, a drainage inlet and 18-inch be installed. Real Estate transactions, utility relocations, temporary traffic control, and and removal may be necessary in support of the project. Construction is anticipated to occur ork will take place during the dry season and will take approximately 3 weeks to complete. Inagement practices for erosion control and water pollution control will be implemented to opplicable regulatory permits will be obtained before construction.		
•	ency Approving Project: Contra Costa County		
Exempt Status:	ect (Sec. 21080[b][1]; 15268)		
•	ect (Sec. 21080[b][1]; 15268)		
<u> </u>	pject (Sec. 21080[b][4]; 15269[b][c])  Other Statutory Exemption (Sec. )		
Reasons why projet facility to meet curre	ct is exempt: The project consists of repairing damaged portions of an existing flood control nt standards of public health and safety involving no expansion of existing use pursuant to 5301 of the CEQA Guidelines.		
	ed document of exemption finding. of Exemption been filed by the public agency approving the project?   Yes  No		
Signature:	Title: Senior Planner Date: Oct. 2, 2025		
Contra	Costa County Department of Conservation and Development		


☐ Signed by Applicant

AFI	FIDAVIT OF FILING AND P	OSTING	
I declare that on Resources Code Section 21152(d		notice as required by California Public sted for 30 days from the filing date.	
Signature		Title	
<u>Applicant</u>	Department of Fish and Wildlife Fees Due		
Public Works Department	☐ De Minimis Finding - \$0		
255 Glacier Drive			
Martinez, CA 94553	☐ Conservation an	☐ Conservation and Development - \$25	
Attn: <u>Alex Nattkemper</u>			
Environmental Services Division			
Phone: (925) 313-2364	Total Due:	Receipt #:	

## FCZ 3B Grayson Creek Bank Erosion Repair



## FCZ 3B Grayson Creek Bank Erosion Repair



## FCZ 3B Grayson Creek Bank Erosion Repair

